



SERIES 12000 IONIZATION SMOKE/CARBON MONOXIDE ALARM

**WARRANTY INFORMATION**

**5-YEAR LIMITED SMOKE/CO ALARM WARRANTY**

Invensys Controls Americas warrants to the original consumer purchaser each new Smoke/CO alarm to be free from defects in material and workmanship under normal use and service for a period of five (5) years from the date of purchase. Invensys Controls Americas agrees to repair or replace, at its option, any defective Smoke/CO alarm provided it is returned with postage prepaid and with proof of purchase date to Invensys Controls Americas. This warranty does not cover damage resulting from accident, misuse or abuse or lack of reasonable care of the product. This warranty is in lieu of all other express warranties, obligations or liabilities. THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE LIMITED TO A PERIOD OF FIVE (5) YEARS FROM THE DATE OF PURCHASE FOR THE SMOKE/CO ALARM. Some states do not allow limitations on how long an implied warranty lasts, so the above limitations may not apply to you. IN NO CASE SHALL INVENSYS CONTROLS AMERICAS BE LIABLE FOR ANY INCIDENTAL OR CONSEQUENTIAL DAMAGES FOR BREACH OF THIS OR ANY OTHER WARRANTY, EXPRESS OR IMPLIED, WHATSOEVER, EVEN IF THE LOSS OR DAMAGE IS CAUSED BY ITS NEGLIGENCE OR FAULT. Some states do not allow the exclusion or limitation of incidental or consequential damages, so the above limitation or exclusion may not apply to you. This warranty gives you specific legal rights, and you may also have other legal rights which vary from state to state. This product meets all the requirements of U.L. Standard 2034.

**Where to send your alarm for service**

**Do not attempt to repair this combination alarm. Doing so will void your warranty.** If you must return an alarm under warranty, send the alarm in a well-padded envelope with postage prepaid, a note describing the nature of the difficulty, and proof of date of purchase to:

In Canada Invensys Controls Americas Product Service Department 3505 Laird Road – Unit #14 Mississauga, ON L5L 5Y7	In U.S.: Invensys Controls Americas Product Service Department 28C Leigh Fisher Blvd. El Paso, Texas 79906
--	--

If the Smoke/CO alarm is no longer under warranty, have a licensed electrician replace the Smoke/CO alarm immediately with a comparable alarm.